

School	Category	Keynote	Room Number	Life Safety Category b,c	Item Description	Item final budget
LEIGH	INTERIOR	A01	Classrooms 104, 105, 106, 107, 108, 109, 111, 112, 113, 114, 115,116, and 204, 205, 206, 207, 208, 209, 219, 220, 222A, 224.	b	Replace chalk boards with markerboards	\$ 34,604
LEIGH	INTERIOR	A02	Girls C2, Boys C2, Girls E2, Boys E2, 223B.	b	Replace finishes, fixtures, stalls and toilets in toilets as per plans	\$ 823,896
LEIGH	INTERIOR	A03	Classrooms 100, 100A, 104, 105, 106, 107, 108, 109, 112, 113, 114, 116, 118. and 204, 205, 206, 207, 208, 209, 211, 212, 213, 214, 215, 217, 218, 219, 221, 222, 224, 226, 228. Stair B1, Stair E1, Corridor B2, and Stair B2	b	Replace wood door panel -multiple locations	\$ 472,785
LEIGH	INTERIOR	A05	Classrooms 104, 105, 106, 107, 108, 109, 111, 112, 113, 114, 116, 118, 120. Also 204, 205, 206, 207, 208, 209, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 222, 223A, 223C, 224, Stair B1, Stair E1, Stair B2, Corridor B2, D2	b	Replace VCT flooring (with LVT or similar)	\$ 408,461
LEIGH	INTERIOR	A06	Classrooms 104, 105, 106, 107, 108, 109, 111, 112, 113, 114, 115, 116, 120, 122B. Also 204, 205, 206, 207, 208, 209, 217, 219, 220, 222, 224		Replace casework and countertop	\$ 478,684
LEIGH	INTERIOR	A07	120, Corridor B2, Stair B2, Stair BB2.	b	Install new ACT ceiling	\$ 172,722
LEIGH	INTERIOR	A08	Stair F1, Stair C1, Lobby C1, Stair A1, Stair B1, Stair BB1, Stair E1, Stair D1, Stair CC2, Stair C2, Stair B2, Corridor B2, Stair BB2	b	Replace Stair handrail and guardrails	\$ 74,882
LEIGH	INTERIOR	A14	Old Locker Rm Under Stage	b	Replace lower level Locker/storage room floor	\$ 5,631
LEIGH	INTERIOR	A18	Gymnasium	b	Repair Gym Wall cracking	\$ 8,239
LEIGH	INTERIOR	A19	Janitors Closet at Boys B	b	Replace roof hatch and ladder room	\$ 16,478
LEIGH	SITE	C01	Main entry	c	Replace concrete stoop at main entry	\$ 5,731
LEIGH	SITE	C03	Ramp at Door 7	c	Replace ramp surface concrete at door 7	\$ 150,796
LEIGH	SITE	C04	South Playground	c	South Playground asphalt re-surfacing	\$ 166,077
LEIGH	SITE	C06	Exterior Stair and Ramp	c	Replace stair steel guardrail and ramp ADA railing	\$ 57,673
LEIGH	SITE	C07	Courtyard	c	Courtyard pavement Improvements and Drainage (See Eriksson Eng) plus survey	\$ 908,144
LEIGH	ELECTRICAL	E01	Toilet Rms	b	Electrical work for the replacement of two (2) exhaust fans as described in the Mechanical Narrative.	\$ 2,843
LEIGH	ELECTRICAL	E02	Mech Rm	b	Electrical work for the addition of new exhaust fans as described in the Mechanical Narrative	\$ 11,371
LEIGH	ELECTRICAL	E03	Elec Rm	b	Replacement of twelve (12) original branch circuit panels.	\$ 180,956
LEIGH	ELECTRICAL	E04	AHU-1	b	Electrical work for the replacement of AHU-1 as described in the Mechanical Narrative	\$ 15,080
LEIGH	ELECTRICAL	E05	AHU-2	b	Electrical work for the replacement of AHU-2 as described in the Mechanical Narrative.	\$ 15,080
LEIGH	ELECTRICAL	E06	AHU-3	b	Electrical work for the replacement of AHU-3 as described in the Mechanical Narrative.	\$ 15,080
LEIGH	ELECTRICAL	E07	AHU-1	b	Electrical work for the replacement of the AHU-1 heating pumps as described in the Mechanical Narrative.	\$ 9,048
LEIGH	ELECTRICAL	E08	AHU-1	b	Electrical work for the replacement of the AHU-1 chilled water pumps as described in the Mechanical Narrative	\$ 9,048
LEIGH	ELECTRICAL	E09	Boiler Room	b	Electrical work for the replacement of the boiler room heating pumps as described in the Mechanical Narrative.	\$ 9,048
LEIGH	ELECTRICAL	E10	Boiler Room	b	Electrical work for the replacement of the boiler room chilled water pumps as described in the Mechanical Narrative.	\$ 9,048
LEIGH	ELECTRICAL	E11	Mech Room E	b	Electrical work for the replacement of the sewage ejector pump in Mech Room E as described in the Mechanical Narrative.	\$ 3,016
LEIGH	ELECTRICAL	E12	Mech Room E	b	Electrical work for the replacement of the sump pump in Mech Room E as described in the Mechanical Narrative.	\$ 3,016
LEIGH	ELECTRICAL	E13	Elec Rom	b	Switch boards	\$ 428,426

School	Category	Keynote	Room Number	Life Safety Category b,c	Item Description	Item final budget
LEIGH	LIFESAFETY	L01	Janitors Closet C	b	#5 - Extend walls to structure and install ceiling Janitors Closet C	\$ 9,641
LEIGH	LIFESAFETY	L02	Rooms 204-209, 104-109	b	#14 - Patch holes in CMU walls, rooms 204-209, 104-109	\$ 3,090
LEIGH	LIFESAFETY	L03	Stair F1, Stair CCI	b	#20 - add fire alarm strobe device, Stair F1, Stair CCI	\$ 1,854
LEIGH	LIFESAFETY	L04	Sinks	b	#38 -Provide frost proof wall hydrant, Public lavs and handwashing sinks	\$ 11,124
LEIGH	LIFESAFETY	L05	Toilets	b	#39 - Provide faucet with vacuum breaker - accessible lavs	\$ 2,101
LEIGH	MECHANICAL	M02	AHU-2 Penthouse.	b	Replace greenheck sidewall exhaust fan in AHU-2 Penthouse.	\$ 10,661
LEIGH	MECHANICAL	M03	Room 250	b	Replace inline exhaust fan in Room 250 in kind.	\$ 10,661
LEIGH	MECHANICAL	M05	Nurse, Classroom 213, Classroom 211, Classroom 219, Classroom 226 and Classroom 228	b	Repair gap in hot water baseboard	\$ 2,843
LEIGH	MECHANICAL	M06	AHU-1	b	Replace TRANE AHU-1 in penthouse in kind- MFR date 1997	\$ 54,287
LEIGH	MECHANICAL	M07	AHU-2	b	Replace TRANE AHU-2 in penthouse in kind- MFR date 1997	\$ 33,929
LEIGH	MECHANICAL	M08	AHU-3	b	Replace TRANE AHU-3 in air handler room in kind- MFR date 1997	\$ 54,287
LEIGH	MECHANICAL	M09	AHU-1 penthouse	b	Replace Bell & Gossett heating water constant volume floor mounted end suction pumps in AHU-1 penthouse	\$ 37,699
LEIGH	MECHANICAL	M10	AHU-1	b	Replace Bell & Gossett chilled water constant volume floor mounted end suction pumps in AHU-1 penthouse	\$ 37,699
LEIGH	MECHANICAL	M11	Boiler Rm	b	Replace Bell & Gossett heating water constant volume floor mounted end suction pumps in boiler room. (Priority 2)	\$ 37,699
LEIGH	MECHANICAL	M12	Boiler Rm	b	Replace Bell & Gossett chilled water constant volume floor mounted end suction pumps in boiler room	\$ 41,195
LEIGH	PLUMBING	P03	Mech Room E	b	Replace duplex sewage ejector in Mech Room E in kind - MFR date 200	\$ 22,619
LEIGH	PLUMBING	P04	Electrical/Boiler Room	b	Replace duplex sewage ejector Electrical/Boiler Room in kind - MFR date 2008	\$ 24,717
LEIGH	PLUMBING	P05	Electrical/Boiler Room	b	Replace thermostatic master mixing valves with digital master mixing valves with integral recirculation pumps and BAS interface.	\$ 32,956
LEIGH	EXTERIOR	X01	Exterior	b	Tuckpointing -multiple locations	\$ 35,535
LEIGH	EXTERIOR	X02	Exterior	b	Reseal/grout concrete fascia joints	\$ 45,239
LEIGH	EXTERIOR	X03	Exterior	b	Window sealant replacement	\$ 1,885
LEIGH	EXTERIOR	X04	Exterior	b	Brick CJ and stone sill/coping joint sealant throughout.	\$ 2,714
LEIGH	EXTERIOR	X05	Exterior	b	Replace exterior door and frame	\$ 21,321
LEIGH	EXTERIOR	X06	Exterior	b	Patch, Install control joints, and paint plaster soffits	\$ 32,956
LEIGH	EXTERIOR	X09	Roof	b	Replace stack vent boots at Metal enclosures	\$ 11,461
LEIGH	EXTERIOR	X10	Roof	b	Chimney cap encapsulation	\$ 2,472
LEIGH	EXTERIOR	X11	Exterior	b	Paint Downspouts	\$ 2,274
LEIGH	EXTERIOR	X12	Exterior	b	Paint Exterior door	\$ 1,706
LEIGH	EXTERIOR	X13	Roof	b	Restore/paint metal duct enclosure send to tremco earth view marked	\$ 303,101
LEIGH	EXTERIOR	X14	Roof	b	Restoration of All Roof Areas - See Tremco's Estimate	\$ 1,613,189
LEIGH	EXTERIOR	X15	Roof	b	Add fixed roof ladder	\$ 18,096
LEIGH	EXTERIOR	X16	Roof	b	Replacement of All Roof Areas - Alternate add'l cost for full replace	\$ 1,352,837
LEIGH	EXTERIOR	X18	Roof	b	counterflashing sealant	\$ 1,501
LEIGH	ACCESSIBILITY	Z01	Sensory Rm 122B; Toilets, Clasrooms 104, 105, 106, 107, 108, 109, 122B, 216.	c	Replace existing sink with ADA compliant	\$ 26,743
LEIGH	INTERIORS	Z02	Girls-D, Boys-D, Girls D2, Boys D2,	b	Replace finishes and toilets in boys/girls toilet rooms per plans	\$ 540,132
HLS Violations - Potentially Eligible:						
Priority 'b'						\$ 7,116,424
Priority 'c'						\$ 1,315,163
TOTAL Life Safety Amendment Eligible Escal'd 2027-2037 =						\$ 8,431,587
Previous LIFE SAFETY Listed Above - Escalated						\$ 27,810

School	Category	Keynote	Room Number	Life Safety Category b,c	Item Description	Item final budget
GILES	INTERIOR	A01	Classroom 102, Classroom A104, Classroom A106, Classroom A108, Classroom A109, Classroom A110, Classroom A111, Corr 1, Corr 3 ; Classroom A112 ; Classroom 227, 229, 230, 231, 232, 233, Girls TLT-18 ; Classroom 252, 253, 254, 255, Girls TLT-19	b	Replace chalk boards with markerboards	\$ 46,138
GILES	INTERIOR	A03	Boys TLT-5, Girls TLT-6 ; Office 122 ; Stor 127A ; Boys TLT-12 ; Classroom 250, 251, 252, 253, 254, 255, 256	b	Replace wood door panel -multiple locations	\$ 128,941
GILES	INTERIOR	A04	Boys TLT-5, Girls TLT-6 ; TLT-3, TLT-4	b	Replace ACT in restrooms and add LED lighting	\$ 31,884
GILES	INTERIOR	A05	Vestibule 100A, Corr 3, Classroom 050, Corr 1, Corr 2, Classroom 052 ; Vestibule 112A, Corr 4 ; Corr 1, Cafeteria 054, Office 122, Hall of Fame 120D ; Stair 1 ; Main Office 152, Office 152A, Corr 6 ; Corr 7, Classroom 233 ; Classroom 250, 251, 252, Elev, Stair 3	b	Replace VCT flooring (with LVT or updated-style similar)	\$ 259,637
GILES	INTERIOR	A08	JC 2, Stair 3 ; Stair 1, Stair 7, Classroom 124 ; Stor 150B, TLT 151D ; Stair 1, Classroom 232 ; Stair 4, Classroom 251,	b	Replace Stair handrail and guardrails	\$ 187,204
GILES	INTERIOR	A10	Stair 3	b	Replace roof hatch ladder room -1949 addition	\$ 9,048
GILES	INTERIOR	A11	Classroom 050 ; Classroom 131 ; Classroom 230	b	Replace Blinds -	\$ 3,955
GILES	INTERIOR	A12	Classroom 052	b	Reconstruct ramp - Classroom 052	\$ 15,282
GILES	INTERIOR	A14	Storage Rm	b	Replace stage edge and storage doors	\$ 28,428
GILES	INTERIOR	A15	Corridor	b	Add handrails to ramp in Corridor 1	\$ 6,877
GILES	SITE	C01	South of Building	c	Replace concrete sidewalk South of Building with asphalt	\$ 6,786
GILES	SITE	C02	West, East, South, Central Playground	c	West, East, South, Central Playground asphalt removal and Replacement	\$ 896,725
GILES	SITE	C03	Northeast stairs	c	Replace steel handrail at Northeast stairs	\$ 10,661
GILES	SITE	C04	South of Gym	c	Replace Asphalt Walk South of Gym w/ asphalt	\$ 5,731
GILES	SITE	C06	South basement stair	c	Replace steel guardrail at South basement stair	\$ 17,302
GILES	SITE	C07	Northeast entrance	c	Replace Ramp - Northeast entrance	\$ 56,856
GILES	ELECTRICAL	E01	Toilet Rooms	b	Electrical work for the replacement of two (2) exhaust fans as described in the Mechanical Narrative	\$ 2,843
GILES	ELECTRICAL	E02	Stair 1, Classroom 11	b	Electrical work for the addition of new exhaust fans	\$ 8,528
GILES	ELECTRICAL	E03	Elec Rm 51B	b	Replacement of thirteen (13) original branch circuit panels.	\$ 196,035
GILES	ELECTRICAL	E04	AHU-1	b	Electrical work for the replacement of AHU-1 as described in the Mechanical Narrative.	\$ 15,080
GILES	ELECTRICAL	E05	AHU-2	b	Electrical work for the replacement of AHU-2 as described in the Mechanical Narrative.	\$ 15,080
GILES	ELECTRICAL	E06	AHU-3	b	Electrical work for the replacement of AHU-3 as described in the Mechanical Narrative.	\$ 15,080
GILES	ELECTRICAL	E07	AHU-4	b	Electrical work for the replacement of AHU-4 as described in the Mechanical Narrative.	\$ 15,080
GILES	ELECTRICAL	E08	AHU-15	b	Electrical work for the replacement of AHU-5 as described in the Mechanical Narrative.	\$ 15,080
GILES	ELECTRICAL	E09	PTA Kitchen 51, Office 51A and Classroom 154.	b	Electrical work for the replacement of three (3) exhaust fans as described in the Mechanical Narrative.	\$ 4,524
GILES	ELECTRICAL	E10	Boiler B5	b	Electrical work for the replacement of the Boiler B5 heating pumps as described in the Mechanical Narrative.	\$ 9,048
GILES	ELECTRICAL	E11	North Penthouse	b	Electrical work for the replacement of the North Penthouse chilled water pumps as described in the Mechanical Narrative.	\$ 9,048
GILES	ELECTRICAL	E12	South Penthouse	b	Electrical work for the replacement of the South Penthouse chilled water pumps as described in the Mechanical Narrative	\$ 9,048
GILES	ELECTRICAL	E13	Ejector room	b	Electrical work for the replacement of the sewage ejector pump in Ejector room as described in the Mechanical Narrative.	\$ 3,016

School	Category	Keynote	Room Number	Life Safety Category b,c	Item Description	Item final budget
GILES	ELECTRICAL	E14	JC-8	b	Electrical work for the replacement of the sump pump in JC-8 as described in the Mechanical Narrative.	\$ 3,016
GILES	ELECTRICAL	E15	Elec Room	b	Replacement of one (1) 1600A, 120/208 volt switchboard and five (5) original branch circuit panels.	\$ 181,257
GILES	ELECTRICAL	E16	Multiple Classrooms	c	Replace remaining fluorescent lighting, lighting controls to code compliant systems with new LED lighting throughout with vacancy/occupancy sensing, dimming where applicable	\$ 295,036
GILES	LIFESAFETY	L01	Stair 4	b	#1- Replace 22 stair treads - Stair 4	\$ 5,438
GILES	LIFESAFETY	L02	Storage B2	b	#2 - Replace 1500 floor tiles - Storage B2	\$ 35,102
GILES	LIFESAFETY	L03	Stair 3	b	#3 - Replace 20 stair treads - Stair 3	\$ 6,056
GILES	LIFESAFETY	L04	Stair 1	b	#5 - Install double door - Stair 1	\$ 10,135
GILES	LIFESAFETY	L05	Storage room 51C	b	#7 - Install UL rated door - Storage room 51C	\$ 3,708
GILES	LIFESAFETY	L06	Various locations	b	#10 - Install 4 door closers in 30 min partitions	\$ 3,214
GILES	LIFESAFETY	L07	Corridor 4	b	#14 - Patch 20 SF of concrete floor - Corridor 4	\$ 1,854
GILES	LIFESAFETY	L08	JC3	b	#15 - Extend 10 SF of wall to deck, install fire rated sealant - JC3	\$ 3,708
GILES	LIFESAFETY	L09	Storage 51C	b	#16 - Install fire rated partitions to create 100 SF storage rooms -	\$ 16,068
GILES	LIFESAFETY	L10	Storage 51C	b	#17 - Remove 160 SF of possible ACM floor tiles - Storage 51C	\$ 6,180
GILES	LIFESAFETY	L11	Storage 51C	b	#18 - Patch 6 SF of plaster walls and ceiling - Storage 51C	\$ 2,225
GILES	LIFESAFETY	L12	Storage C3	b	#20 - Remove storage room and install rated partition - Storage C3	\$ 14,832
GILES	LIFESAFETY	L13	Elect 51B	b	#21 - Patch holes in South masonry wall - Elect 51B	\$ 2,348
GILES	LIFESAFETY	L14	Elect 51B	b	#22 - Patch holes in North masonry wall - Elect 51B	\$ 2,348
GILES	LIFESAFETY	L15	Elect 51B	b	#23 - Patch openings in rated construction - Elect 51B	\$ 6,674
GILES	LIFESAFETY	L17	Storage 130A	b	#31 - Install UL rated sealant - Storage 130A	\$ 989
GILES	LIFESAFETY	L18	JC8	b	#32 - Patch holes in partition JC8	\$ 2,472
GILES	LIFESAFETY	L19	152, 153	b	#33 - Replace glass with safety glass 152, 153	\$ 1,112
GILES	LIFESAFETY	L20	JC7	b	#34 - Patch holes in walls and ceiling JC7	\$ 6,180
GILES	LIFESAFETY	L21	JC3	b	#39 - Provide exhaust system JC3	\$ 8,652
GILES	LIFESAFETY	L22	TLT 15	b	#40 - Provide exhaust system TLT 15	\$ 8,652
GILES	LIFESAFETY	L23	Multiple locations ; Toilet rooms	b	#54 - Provide 8 floor drains	\$ 34,608
GILES	LIFESAFETY	L24	Building Exterior	b	#56 - Provide 7 new wall hydrant	\$ 8,652
GILES	LIFESAFETY	L25	JC7, JC8, JC9, JC124B	b	#57 - Provide faucet with vacuum breaker,	\$ 4,202
GILES	LIFESAFETY	L26	Room 120E,122, 130, Boys locker room	b	#59 - Abandon fixture and remove piping	\$ 8,899
GILES	MECHANICAL	M01	janitor's closet at Boys TLT-17	b	Replace the two non-operation inline exhaust fans in kind located in MFR date 2000	\$ 21,321
GILES	MECHANICAL	M02	Corr 1, Boys TLT-1, Girls TLT-2, Vestibule 120E, Corr 7, Stair 1, Stair 3 and Stair 7	b	Repair gap in hot water cabinet unit heaters or replace cover in the following locations:	\$ 7,107
GILES	MECHANICAL	M03	Classroom 112,114, 116, Band 124, Gymnasium 120, Sym Storage 120B, Classroom 227, 229, 231, 233.	b	Repair gap in heating water baseboard covers in the following locations:	\$ 7,107
GILES	MECHANICAL	M04	PTA Kitchen 51, Office 51A and Classroom 154.	b	Add exhaust to the following spaces for proper ventilation:	\$ 17,057
GILES	MECHANICAL	M05	Penthouse M-3	b	Replace TRANE AHU-1 in Penthouse M-3 in kind- MFR date 2000	\$ 27,143
GILES	MECHANICAL	M06	Mechanical 257	b	Replace TRANE AHU-2 in Mechanical 257 in kind- MFR date 2000	\$ 20,358
GILES	MECHANICAL	M07	South Penthouse M-4	b	Replace TRANE AHU-3 in South Penthouse M-4 in kind- MFR date 2000	\$ 27,143
GILES	MECHANICAL	M08	South Penthouse M-4	b	Replace TRANE AHU-4 in South Penthouse M-4 in kind- MFR date 2000	\$ 20,358
GILES	MECHANICAL	M09	Mechanical 257	b	Replace TRANE AHU-5 in Mechanical 257 in kind- MFR date 2000	\$ 10,556
GILES	MECHANICAL	M10	Stair 1	b	Replace Greenheck exhaust fan in kind located on roof above Stair 1	\$ 11,310
GILES	MECHANICAL	M11	Classroom 11	b	Replace Greenheck exhaust fan in kind located on roof above Classroom 112 - MFR date 1999	\$ 11,310
GILES	MECHANICAL	M13	Boys/Girls toilet room TLT-17 and TLT-18	b	Replace Greenheck exhaust hood in kind located on roof above Boys/Girls toilet room TLT-17 and TLT-18 - MFR date 2000	\$ 11,310
GILES	MECHANICAL	M14	Boiler B5.	b	Replace Bell & Gossett heating water constant volume floor mounted end suction pumps in kind located in Boiler B5.	\$ 37,699
GILES	MECHANICAL	M15	North Penthouse.	b	Replace Bell & Gossett chilled water constant volume floor mounted end suction pumps in kind located in North Penthouse.	\$ 37,699
GILES	MECHANICAL	M16	South Penthouse.	b	Replace Bell & Gossett chilled water constant volume floor mounted	\$ 37,699

School	Category	Keynote	Room Number	Life Safety Category b,c	Item Description	Item final budget
GILES	PLUMBING	P01	Toilets	b	Provide point of use thermostatic mixing valves at lavatories and hand washing sinks to limit water temperature to 110°F.	\$ 28,428
GILES	PLUMBING	P02	JC-5 and JC-8.	b	Install RPZ connection within 5'-0" of chemical dispenser in JC-5 and JC-8.	\$ 2,843
GILES	PLUMBING	P03	JC-5.	b	Replace mop basin located in JC-5. Mop basin was not draining at time of visit.	\$ 2,843
GILES	PLUMBING	P04	Ejector Room	b	Replace sewage ejector in Ejector Room in kind – MFR date 2000	\$ 22,619
GILES	PLUMBING	P05	JC-2	b	Replace sump pump in JC-2 in kind – MFR date 2008	\$ 22,619
GILES	PLUMBING	P06	JC-8	b	Replace gas domestic water heater in JC-8 in kind – MFR 1994	\$ 15,080
GILES	PLUMBING	P07	North Penthouse	b	Replace gas domestic water heater in North Penthouse in kind – MFR 1995	\$ 15,080
GILES	PLUMBING	P08	Boiler Room	b	Replace thermostatic master mixing valves with digital master mixing valves with integral recirculation pumps and BAS interface.	\$ 32,956
GILES	EXTERIOR	X01	Exterior	b	Tuckpointing - various locations	\$ 163,461
GILES	EXTERIOR	X02	Exterior	b	Reseal/grout concrete fascia joints	\$ 45,239
GILES	EXTERIOR	X03	Exterior	b	Window sealant replacement	\$ 135,717
GILES	EXTERIOR	X04	Exterior	b	Brick CJ and stone sill/coping joint sealant (inc. in X3)	\$ -
GILES	EXTERIOR	X09	Exterior	b	Concrete foundation restoration multiple locations	\$ 6,591
GILES	EXTERIOR	X11	Exterior	b	extend downspout (south wall)	\$ 1,137
GILES	EXTERIOR	X15	Roof	b	add fixed roof ladder	\$ 18,096
GILES	EXTERIOR	X16	Roof	b	Re-roofing entire building _ Alternate add'l Cost for full replace	\$ 1,379,202
GILES	EXTERIOR	X18	Roof	b	counterflashing sealant	\$ 3,016
GILES	EXTERIOR	X19	Roof	b	Restore Roof	\$ 1,586,824
GILES	EXTERIOR	X20	Roof	b	Restore/paint metal duct enclosure	\$ 72,382
GILES	ACCESSIBILITY	Z01	Office 100, Classrooms A102-A116;	c	Replace existing sink with ADA compliant	\$ 64,948
GILES	INTERIOR	Z02	toilet rms in 5th/6th hallway	b	Replace finishes and fixtures in	\$ 326,922
HLS Violations - Potentially Eligible:						\$ -
Priority 'b'						\$ 5,405,384
Priority 'c'						\$ 1,354,045
TOTAL Life Safety Amendment Eligible Escal'd 2027-2037						= \$ 6,759,429
Previous LIFE SAFETY Listed Above - Escalated						\$ 204,311